

BUILDING SAFETY CERTIFICATE

No.

Dated: 12/10/2023

It is certified that the existing building SIR C R REDDY PUBLIC SCHOOL at SIR C R REDDY PUBLIC SCHOOL, GNT Road, Santhinagar, Eluru - 534007 is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)
No. of Floor(s) in the Block	3	3	4	3

The building is owned/occupied by SIR C R REDDY PUBLIC SCHOOL have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Roads & Building Department on 13.09.2024 in the presence of V Raghu Kumar, House No. 7B-11-9, Near Saibaba Temple, Eastern Street, Eluru and that the building/premises is fit for occupancy for running school with effect from 13.09.2024 for a period of one years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 13.09.2024 at Eluru by Y.V. Kishore Babuji, B.Tech

Signature with Seal : Executive Engineer
(R&B) Division, Eluru

Name : Y.V. Kishore Babuji, B.Tech

Designation : Executive Engineer

V. Raghu Kumar
CORRESPONDENT
Sir C.R.Reddy Public School
ELURU

A. Kumar
PRINCIPAL
Sir C.R.Reddy Public School
ELURU

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From,
Sri.Y.V.Kishore Babuji. B.Tech.
Executive Engineer (R&B)
(R&B) Division, Eluru.

To,
The Principal,
Sri C R Reddy Public School,
Opp Police Petrol Bunk,
Santhinagar, Eluru,
Eluru District,

Lr.No:259/Soundness Certificate/JA/2020, Dt:28/09/2024.

Sir,

Sub:-Works(R&B)Division,Eluru- Sri C R Reddy Public.School,Opp Police Petrol Bunk
Santhinagar Eluru in Eluru District-Soundness certificate - Issued – Regarding.

Ref:- Request regarding the Soundness Certificate of Sri C R Reddy Public.School,Opp
Police Petrol Bunk Santhinagar, Eluru in Eluru District, Dt.03.8.2024.

With reference to above, it is informed that the RCC Roof Ground first and second floors of Sri C R Reddy Public. School, Opp Police Petrol Bunk Santhinagar Eluru in Eluru District, is structurally sound to run the classes for a period of one year i.e. form **13.09.2024 to 12.09.2025.**

Enclose: Soundness Certificate

Yours faithfully,


Executive Engineer (R&B)
(R&B) Division, Eluru.
A/c 28/9/24


CORRESPONDENT
Sir C.R.Reddy Public School
ELURU


PRINCIPAL
Sir C.R.Reddy Public School
ELURU

SOUNDNESS CERTIFICATE


Sl.No.	Name of the school & address	School details
1	Name of school	:: Sir C.R.Reddy Public School, Opp: Police Petrol Bunk Santhi nagar, Eluru.
2	Name of the Management and phone number & Mail	:: Mobile - 63000 65646; 08812 233350 e.mail - sircrrps@yahoo.com
3	Date of Inspection	:: AEE : 13-09-2024
		:: DEE:
4	Year of construction	::
5	Type of Building	:: RCC roof building
6	Type of foundation footings, Basement and pling beam etc.,	:: Pile foundation & Column foundation.
7	Present condition of foundation whether any settlement cracks are observed upto basement level	:: Sound
8	Souneness of superstructure whether any cracks out of plum, in walls noticed	:: Sound
9	soundness of RCC beam and lintels over openings	:: Sound
10	Condition of flooring	:: Sound
11	Condiitiion of roof slabs, stair case slabs, cracks, leakages	:: Sound
12	Any other remarks which are required to ensure the structural soundness	:: This inspection certificate does not purport covering all the aspects of rthe work and designs.
13	Valid upto	:: 12-09-2025

CERTIFICATES

- 1) Certificate is issued based on the present physical condition of the building. The management is responsible for the structure deformities which occur during course of time in time.
- 2) Further the management has to take necessary precautions during natural calamities occur from time to time for the safety of the students (such as cyclones severe whether conditions, Tsumanimis, Earth quakes etc.,
- 3) Department is not responsible for any structures changes to the building in future course of time.


I do hereby ertify that, I have inspeted the school and found to structurally sound for running the school as the building is fot for the pu rpose of provding shelter from sun and rain.

// Countersigned//


 Asst.Exe.Engineer (R&B)
 Section, Eluru


 Dy.Executive Engineer (R&B)
 Sub-Divn.No.I, Eluru.

"Counter Signed"


 Executive Engineer
 (R&B) Division, ELURU
