

**GOVERNMENT OF ANDHRA PRADESH  
ROADS AND BUILDINGS DEPARTMENT**

From,  
Sri.Y.V.Kishore Babuji. B.Tech,  
Executive Engineer (R&B)  
(R&B) Division, Eluru,

To,  
The Principal,  
Sri C.R.Reddy Public School,  
Opp Polic Petrol bunk,  
GNT road, Santhi nagar,  
Eluru District,

**Lr.No:259/Soundness Certificate/JA/2020, Dt: 18/09/2025.**

Sir,

**Sub:-**Works (R&B) Division, Eluru- Correspondent Sri C.R.Reddy Public School, Opp  
Polic Petrol bunk,GNT road, Santhi nagar, Eluru. – Soundness Certificate - Issued-  
Regarding.

**Ref: -1.**Your Lr.No.Nill Recived on Dt.11-09-2025.


2. Letter.No.SC/School/SA/ELR/2024, Dt.17.09.2025  
of DyEE(R&B) No.I Sub- Division, Eluru.


\*\*\*\*\*

With reference to above, it is informed that the RCC Roof Building  
Ground floor first floor and Second floor Sri C.R.Reddy Public School, Opp Polic Petrol  
bunk,GNT road, Santhi nagar, Eluru is structurally sound to run the classes for a period of one  
year i.e. form **17.09.2025 to 16.09.2026.**

Enclose: Soundness Certificate.

Yours faithfully,

  
Executive Engineer (R&B)  
(R&B) Division, Eluru.



## SOUNDNESS CERTIFICATE

Sl.No.	Name of the school & address	School details
1	Name of school	:: Sir C.R.Reddy Public school, Opp Polic petrol bunk, GNT road, Santhi nagar, Eluru
2	Name of the Management and phone number & Mail	:: Mobile - 08812 233350 e.mail - sircrrps@yahoo.com
3	Date of Inspection	:: AEE : 17.9.2025
		:: DEE:
4	Year of construction	::
5	Type of Building	:: RCC roof building
6	Type of foundation footings, Basement and pling beam etc.,	:: Pile foundations & column foundations.
7	Present condition of foundation whether any settlement cracks are observed upto basement level	:: Sound
8	Souneness of superstructure whether any cracks out of plum, in walls noticed	:: Sound
9	soundness of RCC beam and lintels over openings	:: Sound
10	Condition of flooring	:: Sound
11	Condiitiion of roof slabs, stair case slabs, cracks, leakages	:: Sound
12	Any other remarks which are required to ensure the structural soundness	:: This inspection certificate does not purport covering all the aspects of rthe work and designs.
13	Valid upto	:: 16.09.2026

### CERTIFICATES

1) Certificate is issued based on the present physical condition of the building. The management is responsible for the structure deformities which occur during course of time in time.

2)Further the management has to take necessary precautions during natural calamities occur from time to time for the safety of the students (such as cyclones severe whether conditions, T.sumanimis, Earth quakes etc.,

3) Department is not responsible for any structures changes to the building in future course of time.

I do hereby ertify that, I have inspeted the school and found to structurally sound for running the school as the building is fot for the pu rpose of provding shelter from sun and rain.

// Countersigned//

*M. Seshu*  
Asst.Exe.Engineer (R&B)  
Section, Eluru

*N-2 17/9/25*  
Dy.Executive Engineer (R&B)  
Sub-Divn.No.I, Eluru.

// Countersigned//  
*M. Seshu*  
**Executive Engineer**  
**(R&B) Division, ELURU**  
*18/9/2025*